


**Exterior Restoration Notes**

**West Elevation:**

Removals: Remove entire addition to building including foundation. Shore existing building as required. Remove all exposed utility runs and replace with concealed as shown on drawings. Remove any deteriorated wood siding or trim, taking care to remove only the amount needed to effect a watertight and paintable repair. Remove existing propane storage tank, to be replaced with new, buried tank.

Restoration: Repair/ restore wood framing, sheathing, siding and trim as listed in project specifications. Paint all wood to match historic colors provided by project conservator. Provide new lighting for exit stair as shown on drawings. Provide new footings for existing exit stair as shown on drawings. Renew connections at existing fire stair with stainless steel or triple hot-dipped galvanized connectors.

# PROPOSED WEST ELEVATION

SCALE: 1/4"=1'-0"

SOUTH WELLFLEET NEIGHBORHOOD ASSOCIATION & SOCIAL UNION

P.O. BOX 581
SOUTH WELLFLEET, MA 02663

Architect and Landscape Architect

HADLEY CROW STUDIO
*Architecture and Landscape Architecture*
P. O. BOX 1917 ORLEANS MA 02653
508 255 8001 info@HADLEYCROWSTUDIO.COM

Consulting Engineers

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS
101 South Street, 4th Floor
Boston, MA 02111
T 617.350.5700 F 800.231.6436

Plumbing Mechanical Electrical Engineer

JOHNSON ENGINEERING AND DESIGN, INC.
5 Elm Street, Suite 16, Danvers, MA 01923

Preservation Consultant

Rika Smith-McNally & Associates
Conservators of Objects and Sculpture

59 Fountain Street Box 55
4th Floor East, Studio 15
Framingham, MA 01702

BID SET

HADLEY CROW STUDIO
*Architecture and Landscape Architecture*
P. O. BOX 1917 ORLEANS MA 02653
508 255 8001 info@HADLEYCROWSTUDIO.COM

SWNASU
P.O. BOX 581
SOUTH WELLFLEET, MA 02663

| REV | DATE | ISSUED FOR |
|---|---|---|
| | | |
| | | |
| | | |
| | | |
| | | |

WEST ELEVATION

DATE: 01/27/2012

SCALE: 1/4" = 1'-0"

DWG. NO. A-401